


A vertical line with seven horizontal tick marks. The segments between the tick marks are labeled A, B, C, D, E, F, and G from top to bottom.



1) Thread for cable entries acc.
to order acknowledgement
or technical data sheet

All dimensions in mm

For all other dimensions of actuators/gearboxes, refer to the latest dimension sheet issue